

PRINCO DVD-R/RW compatibility tests on different burners and firmware versions, updated 26.10.04

NR : can support, but no recommend
 × : not support
 ○ : Supported, runs perfect

Brand	Model	Firmware Version	DVD-R				DVD-RW				NOTE
			1X-DVD-R	4X-DVD-R			1X-DVD-RW	2X-DVD-RW			
				1X	2X	4X		1X	2X		
AOPEN	DRW8800/AAP	1.15	○	○	○	○	○	○	○	Pioneer DVR-107 OEM drive	
	DRW8800/APP	1.18	2X	×	○	○	○	○	1X	NEC ND-2500A OEM drive	
ASUS	DRW-0402P	1.30	○	○	○	○	○	○	○	Pioneer DVR-105 OEM drive	
	DRW-0402P/D	1.05	○	○	○	○	○	○	○	Pioneer DVR-106 OEM drive	
	DRW-0804P	1.05	○	○	○	○	○	○	○	Pioneer DVR-107 OEM drive	
	DRW-1604P	1.09	○	○	○	○	○	○	○	Pioneer DVR-A08 OEM drive	
BENQ	DVD-RW 2108VR	1.40	○	○	○	×	○	○	×	Pioneer DVR-104 OEM drive	
BTC	DRW1004IM	0051	○	×	NR	○	○	○	○		
	DRW1008IM	0059	2X	×	○	○	○	○	○		
	DRW1108IM	B028	NR	NR	○	○	○	○	○		
BUFFLO	DVR-R42FB	1033	○	○	1X	1X	○	○	○	Toshiba SD-R5112 OEM drive	
	DVM-H422FB	0054	○	×	NR	○	○	○	○	BTC DRW-1004IM OEM drive	
	DVSM-D5812FB	A102	2X	×	○	○	○	○	○	LG GSA-4120B OEM drive	
GIGABYTE	GO-W0404A	0043	○	×	NR	○	○	○	○	BTC DRW-1004IM OEM drive	
HITACHI	GSA-4040B	A302	2X	×	○	○	○	○	○		
	GSA-4120B	A102	2X	×	○	○	○	○	○		
HP	DVD420i	1.27	2X	×	○	○	○	○	○	NEC ND-2500A OEM drive	
IODATA	DVR-ABH2	A108	2X	○	○	×	○	○	×	LG GMA-4020B OEM drive	
	DVR-ABH4	A112	2X	×	○	○	○	○	○	LG GSA-4040B OEM drive	
	DVR-UEH4S	A112	2X	×	○	○	○	○	○	LG GSA-4040B OEM drive	
	DVR-ABP4	1.30	○	○	○	○	○	○	○	Pioneer 105 OEM drive	
	DVR-ABN4	1.06	2X	×	○	○	○	○	1X	NEC ND-1300A OEM drive	
	DVR-ABN8	1.06	2X	×	○	○	○	○	1X	NEC ND-2500A OEM drive	
	DVR-ABN8W	2.04	2X	×	○	○	○	○	○	NEC ND-2510A OEM drive	
	DVR-ABH8	A121					○	○	○	LG GSA-4082B OEM drive	
DVR-ABH12W	A102	2X	×	○	○	○	○	○	LG GSA-4120B OEM drive		
IOMEGA	DVDRW4216IND-A	1.08	2X	×	○	○	○	○	1X	NEC ND-1300A OEM drive	
	DVDRW4224	A112	2X	×	○	○	○	○	○	LG GSA-4040B OEM drive	
LITE-ON	LDW-400D	1.2C	○	○	○	2X	○	○	○	SONY DRU-500A OEM drive	
	LDW411S	FS0F	○	×	○	○	○	○	○		
	LDW-440D	FS07	○	○	○	○	○	○	○	SONY DW-U14A OEM drive	
	LDW-811S	HS0E	○	×	○	○	○	○	○		
	LDW-851S	GS08	2X	×	○	○	○	○	○		
	SOHW-812S	US0Q	2X	×	○	○	○	×	○		
	SOHW-832S	VS0A	2X	×	○	○	○	×	○		
SOHW-1213S	TS0C	2X	×	○	○	○	×	○			
LG	GMA-4020B	A109	2X	○	○	×	○	○	×		
	GSA-4040B	A304	2X	×	○	○	○	○	○		
	GSA-4081B	A104	2X	×	○	○	○	○	○		
	GSA-4082B	A207	2X	×	○	○	○	○	○		
	GSA-4120B	A102	2X	×	○	○	○	○	○		
MELCO	DVM-4222FB	1.1c	○	○	○					SONY DW-U10A	
	DVR-21FB	1033	○	○	1X	×				Toshiba SD-R5002	
	DVRAM-FB		○	○	○						
	DVM-4242FB		○	○	○	×				SONY DW-U12A	
	DVM-4244FB		○	○	○	×				SONY DW-U14A	
	DVM-L4242FB	1.07	○	○	○	○	○	○	○	Pioneer 106	
	DVR-42FB	1.30	○	○	○	○	○	○	○	Pioneer 105	
	DVR-R42FB	1033	○	○	1X	1X	○	○	×	TOSHIBA SD-R5112	
DVSM-34242FB	A112	2X	×	○	○	○	○	○	LG GSA-4040B OEM drive		
MSI	DR4-A	2.17	2X	○	○	○	○	○	○	Sanyo CRD-BPDV2 OEM drive	
	DR8-A	130D	2X	×	○	○	○	○	○		
Mitsumi	DW-7802TE	1.16	2X	×	○	2X/4X	○	○	1X	NEC ND-1300A OEM drive	
NEC	DVD_RW ND-1300A	1.08	2X	×	○	2X/4X	○	○	1X		
	ND-2500A	1.06	2X	×	○	○	○	○	1X		
	ND-2510A	2.16	2X	×	○	○	○	○	1X		
	ND-3500A	2.17	2X	×	○	○	○	○	1X		
OPTORITE	DD0201	2.15	2X	○	○	○	○	○	○	Sanyo CRD-BPDV2 OEM drive	
	DD0401	120E	2X	×	○	NR	○	×	○		
	DD0405	150E	2X	×	○	○	○	○	○	Sanyo CRD-BPDV3 OEM drive	
	DD1203	110I	2X	×	○	NR	○	○	○		
	LF-D311SC	A122	○	○	×	×	×	×	×		
	LF-D521JD	A112	2X	○	○	×	○	○	×		
	LF-M621JD	F100	2X	○	○	○	○	○	×		
	LF-P667C	1.00					○	○	○		
	DVD-RAM SW-9571	A106	2X	○	○	×	○	○	×		

Brand	Model	Firmware Version	DVD-R				DVD-RW			NOTE	
			1X-DVD-R	4X-DVD-R			1X-DVD-RW	2X-DVD-RW			
				1X	2X	4X		1X	2X		
PANASONIC	DVD-RAM SW-9572	F100	2X	○	○	○	○	○	×		
	LF-M660JD	F100					○	○	×		
	DVD-RAM UJ-815A	DZJ1					○	×	×		
	DVD-RAM UJ-830B	1.00					○	○	○		
	SW-9583C	B100	○	○	×	NR	○	○	○		
	LF-M721JD	APG8					○	○	○		
	LF-M760	AUG8					○	○	○		
PIONEER	DVR-103	2.00	○	○	○	×	○	○	×		
	DVR-104	1.40	○	○	○	×	○	○	×		
	DVR-105	1.33	○	○	○	○	○	○	○		
	DVR-A05-J	1.33	○	○	○	○	○	○	○		
	DVR-106	1.07	○	○	○	○	○	○	○		
	DVR-A06-J	1.07	○	○	○	○	○	○	○		
	DVR-A07D	1.10	○	○	○	○	○	○	○		
	DVR-A07XLA	1.10	○	○	○	○	○	○	○		
	DVR-A07XLB	1.10	○	○	○	○	○	○	○		
	DVR-A07-J	1.13	○	○	○	○	○	○	○		
DVR-A08-J	1.06	○	○	○	○	○	○	○			
PIODATA	DVR-108DX	1.10	○	○	○	○					
PLEXTOR	PX-708A	1.07	2X	○	○	○	○	○	○		
	PX-708UF	1.07	2X	○	○	○	○	○	○		
	PX-712A	1.05	2X	×	○	○	○	○	○		
RICHO	MP5308D	1.B3	2X	×	○	○	○	○	1X	NEC ND-2500A OEM drive	
SAMSUNG	SH-W08	1S31	2X	×	○	NR	○	×	○		
SANYO(GENERIC)	CRD-BPDV2	2.15	2X	○	○	○	○	○	○		
	CRD-BPDV3	LD83	2X	×	○	○	○	○	○		
SONY	DRU-500A	2.0g	○	○	○	2X	○	○	○	Internal model	
	DRU-510A	1.0d	○	○	○	2X / 4X	○	○	○		
	DRX-500UL	2.0f	○	○	○	2X	○	○	○	External model (SONY DRU-500A)	
	DRX-500ULX	2.0f	○	○	○	2X	○	○	○	External model (SONY DRU-500AX)	
	DRU-530A	2.1a	2X	○	○	NR	○	○	○		
DRU-700A	VY06	2X	×	○	○	○	○	○			
TDK	DVRW0404N	1.09	2X	○	○	○	○	○	○	1X	NEC ND-1300A OEM drive
	DVRW840G	1.03	2X	○	○	○	○	○	○	○	Plextor PX-708A OEM drive
	AID+880N	1.33	2X	×	○	○	○	○	○	1X	NEC ND-2500A OEM drive
TEAC	DV-W50E	1.30	○	○	○	○	○	○	○	Pioneer DVR-105 OEM drive	
	DV-W50D	1.05	○	○	○	○	○	○	○	Pioneer DVR-106 OEM drive	
	DV-W58G	H4S3	2X	×	○	○	○	○	○	LiteON SHOW-811S OEM drive	
	DV-W58D	1.13	○	○	○	○	○	○	○	Pioneer DVR-107 OEM drive	
	DV-W58G-A	US47	2X	×	○	○	○	○	○	LiteON SHOW-812S OEM drive	
Toshiba	SD-R5002	1033	○	○	1X	×	○	○	×		
	SD-R5112	1033	○	○	1X	1X	○	○	○		
	SD-R6112	1031	○	○	1X	×	○	○	×		
	SD-R5272	1030	2X	×	○	NR	○	×	○		

Note:

NR : can support, but no recommend

× : not support